

ABSTRACT OF THE DISCLOSURE

Method of welding cladding to a surface of a metal component of a nuclear reactor at a region susceptible to stress corrosion cracking, in which the metal is welded to the surface of the component under conditions of low heat input to achieve reduced thermal sensitization at the edges of and within the newly clad region.